



## HAZE REMOVER

### LIQUID PRINTING SCREEN CLEANER

#### General Characteristics:

Appearance:	Orange Translucent Fluid
Chemical Composition:	Neutral Surfactant Blend
Solubility in Water:	Soluble
Foaming Nature:	High
pH, 1% solution:	7.5 ± 0.5

#### Application: \*

Spray or pour Haze Remover onto screen. Allow 3 - 5 minutes dwell time, or, for light haze, apply agitation immediately. Use a brush or high pressure hose to scrub the screen. Rinse thoroughly with water. Repeat the process if necessary.



\*As conditions vary, all dosages and guidelines are merely suggested starting points; it is recommended the user determine the proper operating conditions for his/her system.

#### Special Features

- Removes Stained Images from Printing Screens
- Deep Penetrating Formula
- Safe and Highly Effective
- Contains No Harsh Chemicals
- Economical to Use

#### Uses:

Specifically formulated to safely remove stained images and haze from printing screens.



#### Packaging:

1 Gallon	5 Gallon	15 Gallon
55 Gallon	275 Gallon	Bulk